

ÉMI Non-profit Limited Liability Company for Quality Control and Innovation in Building

Technical Direction, Central Testing Laboratory

Address: 1113 Budapest, Diószegi út 37. Phone: (+36-1)-372-6100; E-mail: info@emi.hu

PAGE 1/7

Project number: M1-G381X-12049-2017/2-2

Topic number: -

TEST REPORT

Name of the product(s)

and/or the test:

Ring rigidity and ring flexibility test of the pipes of the BlauFAST $\,$

air duct system manufactured by Blauberg Ventilatoren GmbH

Applicant:

Blauberg Ventilatoren GmbH

D-81379 München, Aidenbachstr. 52., Germany

Name of the test standard(s):

EN ISO 9969:2016

Thermoplastic plastic pipes. Determination of ring rigidity

EN ISO 13968:2009

Plastic piping and drainage systems. Thermoplastic plastic pipes.

Determination of ring rigidity

Place of the test:

ÉMI Non-profit Limited Liability Company for Quality Control

and Innovation in Building

Material Testing Unit

1113 Budapest, Diószegi út 37.

13.12.2017

The test results apply only to the individual tested.

The test report may be copied only in full volume without the written consent of Laboratory.

The expertise, interpretation and assessment indicated in the test report means an activity performed in non-accredited status.

The report contains 7 numbered pages and 0 attachments.



PAGE 2/7

1. DATA

1.1 Manufacturer of the product: Blauberg Ventilatoren GmbH

D-81379 München, Aidenbachstr. 52., Germany

1.2 Production site: Ventilation Systems, PrJSC

08150 Boyarka, Kyiv region, Sobornosty u. 36., Ukraine

1.3 Sampling related data: Sampling was made by the customer.

2. **TESTS**

Test conditions

Date of the test:

12.12.2017

Relative humidity of the laboratory: 41%

Temperature of the laboratory:

21°C

Test was made by:

Attila Bohák (Test technician)

Denomination, authentication and/or calibration results of the equipment, devices applied during the test:

Name of measuring gauge	Measuring range of the gauge	ID-number of gauge	Controlled state of the gauge calibrated calibrated	
Universal tension- compression equipment	0-600 kN	41.		
Temperature and humidity meter	-50 - +70 °C 25-98 %	121.		
Digital calliper	0-300 mm	142.	calibrated	

- 2.1. Determination of ring rigidity according to EN ISO 9969:2016 standard
- 2.2. Determination of ring flexibility according to EN ISO 13968:2009 standard.

Project number: M1-G381X-12049-2017/2-2

DK-A999X-14490-2018



3. RESULTS

3.1 Dimension control

The control of the dimensions (outer diameter, wall thickness) was made on 6 plaxes per specimen. The measurement data and the calculated inner diameters are shown in table no. 1:

_	-	1000	100220				
	2	n	le	n	$\boldsymbol{\sim}$	7	
		.,			.,	- 1	ь.

Specimen	Length [mm] (average of 3 measurements)	Outer diameter [mm] Wall thickness [mm]							Calculated inner
		1	298.9	74.56	74.55	75.23	74.91	74.87	74.70
6.08	5.81			5.66	6.13	5.30	5.87	5.81	
2	299.4	75.23	73.89	75.26	75.09	73.59	75.12	74.70	63.14
2		6.17	5.91	5.34	5.91	6.01	5.34	5.78	
3	300.2	75.71	74.13	74.54	74.94	74.43	74.98	74.79	63.40
	300.2	6.18	5.71	5.25	6.01	5.82	5.21	5.70	
4	301.6	62.86	62.92	62.97	62.97	62.97	62.68	62.90	51.90
		5.73	5.60	5.36	5.53	5.36	5.41	5.50	
5	301.3	63.01	63.05	63.10	62.91	63.30	62.82	63.03	52.00
		5.39	5.64	5.59	5.37	5.60	5.52	5.52	
6	302.2	62.98	62.92	63.05	62.90	63.07	63.01	62.99	52.00
		5.12	5.39	5.70	5.34	5.61	5.80	5.49	

3.2 Ring rigidity and ring flexibility test

The tests were made on specimens subjected to dimension control; the specimens were loaded at an angle of "0" and "120" degrees, up to 3% compression, at a speed according to their diameter, then they were loaded at an angle of "240" degrees up to 30% compression, where we read also the ring rigidity value belonging to 3%-os compression. Test results are shown in table no. 2:

Table no. 2


Measurement ID	Measuring position	F _{a,b,c} [N]	y _{a,b,c} [mm]	Ring rigidity [kN/m ²]	Average ring rigidity [kN/m²]	Ring flexibility [N]
1/1	0°	282.7	2.06	8.917		_
1/2	120°	59.9	2.08	1.875	4.95	— — — — — — — — — — — — — — — — — — —
1/3	240°	129.4	2.08	4.050		1218
2/1	0°	45.6	2.07	1.426		
2/2	120°	246.0	2.03	7.840	3.85	
2/3	240°	74.0	2.10	2.291		1180
3/1	0°	75.0	2.08	2.335		
3/2	120°	286.8	2.06	9.021	4.71	
3/3	240°	89.6	2.09	2.779		1225
4/1	0°	304.7	1.72	11.417		_
4/2	120°	303.0	1.72	11.322	12.02	
4/3	240°	357.1	1.73	13.328		1391
5/1	0°	318.8	1.73	11.893		<u> </u>
5/2	120°	355.1	1.72	13.291	11.90	
5/3	240°	281.5	1.72	10.530		1392
6/1	0°	338.4	1.73	12.558		_
6/2	120°	323.5	1.73	12.052	12.86	_
6/3	240°	373.6	1.72	13.973		1390

Project number: M1-G381X-12049-2017/2-2


DK-A999X-14490-2018



During the ring flexibility test the specimen die not brake and the force values were increasing continuously until the complete deformation (30%) was achieved, there is no significant drop in them. Refer to the pictures 1-6.




Picture no. 1: force-deflection diagram of the ring rigidity test of the specimen no. 1




Picture no. 2: force-deflection diagram of the ring rigidity test of the specimen no. 2






Picture no. 3: force-deflection diagram of the ring rigidity test of the specimen no.3




Picture no. 4: force-deflection diagram of the ring rigidity test of the specimen no. 4





Picture no. 5: force-deflection diagram of the ring rigidity test of the specimen no. 5



Picture no. 6: force-deflection diagram of the ring rigidity test of the specimen no. 6

4. DECLARATION

Project number: M1-G381X-12049-2017/2-2

DK-A999X-14490-2018



5. ANNEXES

Budapest, December 13, 2017

Test made by:

Attila Bohák Test technician

Professionally checked by:

Bálint Schwarczkopf Head of Material Testing Unit Report compiled by:

Krisztián Krakker Test engineer

Approved by:

Péter Sólyomi Head of

Central Testing Laboratory